Quick Reference Sheet

Verifying Hours of Operation and Checking Oxygen Concentration

1) **Checking the hours of operation on the OxyGo POC**
   While the OxyGo POC is operating, press and hold the Alarm Bell Button for 5 seconds. The concentrator's display will show the hour meter, the unit's serial number, and the software version installed on the device.

2) **Checking Oxygen concentration on the OxyGo POC**
   The oxygen concentration can be checked using an oxygen analyzer. The concentrator should be run for 10 minutes before measuring the oxygen concentration. If the concentrator has not been used for more than 2 weeks, the concentrator should be run for a minimum of 30 minutes to allow for adjustments to the operating parameters prior to measuring the oxygen concentration.

3) **Procedure for putting the OxyGo POC into "auto-pulse mode" in order to check oxygen concentration:**
   a) With the OxyGo POC off, plug in external power to the concentrator (Do not turn unit on).
   b) Simultaneously press and hold the "alarm bell" and the "light" buttons for 5 seconds.
   c) The administrative mode menu will show normal. Press the "+" button until the LCD reads "Auto Pulse".
   d) Press the "alarm bell" button once and the unit will show 17 BPM. Press the "+" or "-" button to change the rate to either 10, 17, or 25 BPM.
   e) Press the "alarm bell" button once and the unit will begin auto pulsing at the selected rate.
   f) Power off unit to exit auto pulse mode.

OxyGo Battery Duration Chart

Setting	8 Cell Battery Duration*	16 Cell Battery Duration*
Setting 1	4.5 hours	9.0 hours
Setting 2	4.0 hours	8.5 hours
Setting 3	3.0 hours	6.0 hours
Setting 4	2.0 hours	4.0 hours
Setting 5	1.7 hours	3.3 hours

*Based on 17BPM