

# OUTBOARD E-TEC MENU

## **TILLER HANDLE TUNE-UP**

Gap and index spark plugs if needed, inspect fuel system (replace filter if needed), stabilize fuel system, verify shift/throttle systems and adjustments, grease fittings, check tilt/trim system, replace gear case oil, remove propeller to inspect shaft, seal and grease splines, inspect water pump flow, test run in tank or on muffs, check for software updates and warranty recalls.

**Labour UP TO \$349 + PARTS**

## **REMOTE OUTBOARD TUNE-UP**

Same as above plus charge and test battery and charging system, verify all gauge functions, inspect remote control assembly including throttle and shift cable adjustment, drain or replace water separating fuel filter, service boat trailer.

**Labour UP TO \$499 + PARTS**

## **BASIC WINTERIZE WITHOUT SERVICE**

Stabilize fuel system, grease fittings, inspect gear case oil for water, greased propeller shaft splines, charge and disconnect battery if equipped, run engine through fogging mode, spray down engine and gear case with anti-corrosive, install mildew control bags if boat equipped with a cover & service trailer.

**Labour UP TO \$349 + PARTS**

## **REPLACE WATER PUMP ASSEMBLY**

Remove gear case and dis-assemble water pump. Replace complete water pump assembly with new. Blow out all passages. Clear faults if any present. Re-assemble, run and test.

**Labour UP TO \$399 (model dependant) + PARTS**