



Rev. 3 Changes made to harness are on the AC inverter harness being changed to a sealed Deutsch DT8-62 8/25/10
 Rev. 4 Changes made to harness are the cable used for wiring length of wire is 1.00m rather than 0.75m
 Rev. 5 Changes made to the parking brake switch from 1.00m to 0.75m